

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

CMM Index:

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
20-00-10	CMM		STANDARD PRACTICES APPLICABLE FOR D2439 AND D4829 EQUIPMENT	AIRBUS	-	0	AUG 20/24
20-40-00	OPNC		OPTIONAL PART NUMBER CATALOG (OPNC)	AIRBUS	-	1	JUN 30/03
20-40-01	OPNC		OPTIONAL PART NUMBER CATALOG (OPNC) FFM A. UEB	AIRBUS	JUN 08/11	1	SEP 05/11
21-41-05	CMM	3224-11	FLIGHT DECK FLOOR HEATING PANEL	AIRBUS	OCT 01/86	0	-
22-09-04	CMM		CANCELLED REPLACED BY CMM ATA REF. 20-00-10 STANDARD PRACTICES REPAIR PROCEDURES FOR PRINTED CIRCUIT BOARDS	AIRBUS	-	1	AUG 1/95
24-25-11	ACMM	4188-00	STATIC INVERTER 1000 VA	AIRBUS	OCT 15/99	2	NOV 28/06
24-25-12	CMM	4188-01	STATIC INVERTER 1000 VA	AIRBUS	JUL 18/08	0	-
24-28-11	ACMM	4190-00 4190-01	STATIC INVERTER 2500 VA	AIRBUS	FEB 03/03	3	OCT 20/05
25-15-51	CMM	3224-50 3224-51	HEATING PANEL	AIRBUS	NOV 15/87	3	AUG 24/07
25-15-52	CMM	3224-60	FLIGHT CREW FOOT WARMER	AIRBUS	JUL 14/06	0	-
25-25-01	ACMM	4234-11-0200 4234-11-0300 4234-21-0203 4235-11-0200 4235-21-0203	FLIGHT ATTENDANT PANEL (FAP)	EMBRAER	NOV 29/02	4	JUL 15/24
25-27-11	ACMM	3398-10 3398-20 3398-30 3398-40	FLOOR PANEL, HEATED	AIRBUS	NOV 25/96	1	DEC 15/24
25-62-01	CMM	3214-62-32	SLIDE RELEASE POWER SUPPLY UNIT (SRPSU)	AIRBUS	FEB 14/03	1	JUL 29/04
26-22-01	CMM	3284-11 3284-12	AUTOMATIC FIRE EXTINGUISHING CONTROL UNIT	AIRBUS	FEB 28/93	1	FEB 28/94
26-22-02	CMM	3284-13 3284-14	AUTOMATIC FIRE EXTINGUISHING CONTROL UNIT (AFECU)	AIRBUS	MAY 15/23	2	APR 16/24
27-51-16	CMM	084331340000000 300-90116-0506	PROXI/SPARE BOARD	AIRBUS	-	3	FEB 5/02

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
27-51-17	CMM	184331011100000 284331011100000 800-50001-0051 800-50001-0151	LEMP/EMI-MODULE	AIRBUS	-	3	DEC 03/24
27-51-20	ACMM	065-50001-0100 065-50001-0200	COMMAND SENSOR UNIT	AIRBUS	-	3	JAN 15/24
27-51-50	CMM	065-50000-0404 065-50000-0508 065-50000-0509	SLAT/FLAP CONTROL COMPUTER	AIRBUS	-	7	OCT 29/24
27-51-51	CMM	300-90113-0518 884331310000000 984331310000000 108433131000000 118433131000000	CPU LANE A BOARD	AIRBUS	-	3	DEC 15/03
27-51-52	CMM	300-90114-0506 300-90114-0507 300-90114-0509 484331330000000 684331330000000 784331330000000 984331330000000	CPU LANE B BOARD	AIRBUS	-	2	AUG 26/03
27-51-53	CMM	300-90115-0510 300-90115-0511 300-90115-0512 884331320000000 984331320000000	I/O BOARD	AIRBUS	-	4	DEC 15/03
27-51-54	CMM	300-90117-0509 300-90117-0510 300-90117-0511 300-90117-0512 300-90117-0513 300-90117-0514 784331100000000	POWER SUPPLY UNIT	AIRBUS	-	2	APR 30/02
27-51-55	CMM	300-90119-0507 300-90119-0508 300-90119-0511 300-90119-0512 300-90119-0513	ON BOARD REPLACEABLE MEMORY (OBRM)	AIRBUS	-	3	DEC 15/03
27-51-60	CMM	84333-00-0304 84333-00-0305	SLAT/FLAP CONTROL COMPUTER	AIRBUS	-	1	JUL 16/24

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
27-51-61	CMM	184333041000000	POWER SUPPLY UNIT BOARD	AIRBUS	-	1	APR 23/08
27-51-62	CMM	284333043100000	CPU BOARD	AIRBUS	-	0	MAY 15/06
27-51-63	CMM	284333043200000 284333083200000	I/O BOARD SLAT/FLAP, I/O BOARD SLAT	AIRBUS	-	2	AUG 01/11
27-51-64	CMM	184333021100000	CONNECT BOARD	AIRBUS	-	0	MAY 15/06
27-51-70	CMM	200301E00000206	SLAT/FLAP CONTROL COMPUTER SINGLE AISLE	AIRBUS	-	0	SEP 01/24
27-51-71	CMM	200301M01000703	CPU/PSU BOARD	AIRBUS	-	0	SEP 01/24
27-51-72	CMM	200301M02000404	INPUT/OUTPUT BOARD	AIRBUS	-	0	SEP 01/24
27-52-01	CMM	84320-00-0303 84320-00-0404 84320-00-0405	SLAT/FLAP CONTROL COMPUTER	AIRBUS	-	4	OCT 12/11
27-52-01	ATS	84320-00-0405	ATLAS TEST SPECIFICATION FOR THE SLAT/FLAP CONTROL COMPUTER	AIRBUS	-	1	OCT 05/11
27-52-01A	ATS	84320-00-0404	ATLAS TEST SPECIFICATION FOR THE SLAT/FLAP CONTROL COMPUTER	AIRBUS	-	0	JUN 15/07
27-52-02	CMM	1384320043100	CPU BOARD	AIRBUS	-	0	JAN 15/24
27-52-03	CMM	1084320043200	INPUT/OUTPUT BOARD 1	AIRBUS	-	0	JAN 15/24
27-52-04	CMM	0584320043300 0884320083300	INPUT/OUTPUT BOARD 2 SLAT/FLAP	AIRBUS	-	0	JAN 15/24
27-52-05	CMM	0684320043400	INPUT/OUTPUT BOARD WTB	AIRBUS	-	0	JAN 15/24
27-52-07	CMM	0684320041000	POWER SUPPLY UNIT BOARD	AIRBUS	-	0	JAN 15/24
27-52-08	CMM	0484320021100	CONNECT BOARD	AIRBUS	-	0	JAN 15/24
27-52-10	ACMM	DAX6E8432094-03 DAX698432094-04 DAX688432094-05	MSP SOFTWARE	AIRBUS	-	2	OCT 22/08
27-52-20	ACMM	80835-00-02	FLAPS LEVER	AIRBUS	-	2	NOV 03/11
27-52-30	ACMM	87140-00-03 87140-00-04 87145-00-03 87145-00-04	SLAT POSITION PICK OFF UNIT FLAP POSITION PICK OFF UNIT	AIRBUS	-	4	JUN 15/11
29-30-04	CMM	TM113	TEMPERATURE TRANSDUCER/SWITCH	AIRBUS	-	2	MAR 03/24
29-30-05	CMM	VT477 VT477-1	HYDRAULIC RESERVOIR QUANTITY INDICATOR	AIRBUS	-	5	JUN 03/24

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
29-30-06	CMM	VT477-2 VT477-3	HYDRAULIC RESERVOIR QUANTITY INDICATOR	AIRBUS	-	2	JUN 03/24
29-30-07	CMM	TM113-1	TEMPERATURE TRANSDUCER/SWITCH	AIRBUS	-	2	MAR 30/01
29-30-07	CMM	TM113-1	TEMPERATURE TRANSDUCER/SWITCH	AIRBUS	-	2	MAR 30/01
30-41-01	TIS	3273-50	WINDSHIELD HEAT CONTROL UNIT (WHCU)	BRITISH AEROSPACE	AUG 95	2	MAY 05/03
30-42-02	CMM	3285-10	WINDSCREEN HEATER CONTROL UNIT (WHCU)	DORNIER	NOV 25/94	1	JUN 30/00
30-42-03	CMM	3285-50	WINDOW HEAT CONTROL UNIT	DORNIER	APR 10/00	0	-
30-71-00	TM	3092	TRANSFORMER FOR DRAINMAST HEATING	AIRBUS	DEC 72	2	AUG 20/08
31-50-99	CMM	3274-10	RED WARNING PANEL	DORNIER	MAR 20/95	0 TR	- NOV 20/03
31-52-01	CMM	3290-10	AUDIO WARNING SYSTEM	BRITISH AEROSPACE	NOV 02/92	1	SEP 30/94
33-13-11	CMM	3296-30 3296-40	LIGHTING DIMMER	DORNIER	JUL 15/96	3	MAR 11/08
33-13-28	CMM	3228-10	DIM UNIT	DORNIER	OCT 01/85	2	FEB 28/97
33-20-02	CMM	4238-10	CONTROL MODULE (CM)	EMBRAER	MAR 28/02	1	MAY 28/02
33-20-10	CMM	1J5005-100024-X 1J5005-100036-X 1J5005-100042-X 1J5005-100048-X	SIDEWALL LIGHT	BOEING	MAR 20/08	3	FEB 17/12
33-20-11	CMM	1J5005-211112-X 1J5005-211118-X 1J5005-211124-X 1J5005-211136-X 1J5005-211142-X 1J5005-211148-X	CEILING LIGHT INBOARD (CL/L IB)	BOEING	AUG 08/08	3	MAR 29/11
33-20-12	CMM	1J5005-221112-X 1J5005-221118-X 1J5005-221124-X 1J5005-221136-X 1J5005-221142-X 1J5005-221148-X 1J5005-222112-X 1J5005-222118-X 1J5005-222124-X 1J5005-222136-X 1J5005-222142-X 1J5005-222148-X	CEILING LIGHT OUTBOARD (CL/L OB)	BOEING	APR 23/08	3	JAN 27/11

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-20-13	CMM	1J5005-230012-1 1J5006-230012-0	CEILING LIGHT GN 12 / ACCENT LIGHT 12	BOEING	MAY 19/08	3	MAY 31/12
33-20-14	CMM	1J5005-311012-X 1J5005-311018-X 1J5005-311024-X 1J5005-312024-X	OVERHEAD FLIGHT ATTENDANT REST LIGHT (OFAR/L)	BOEING	JUN 18/08	2	MAY 03/24
33-20-15	CMM	1J5005-301012-X 1J5005-301018-X 1J5005-301024-X	NO OVERHEAD FLIGHT ATTENDANT REST LIGHT (N-OFAR/L)	BOEING	JUL 09/08	4	MAR 15/12
33-20-16	CMM	1J5005-411018-X 1J5005-411024-X 1J5005-412024-X 1J5005-413012-X	OVERHEAD FLIGHT CREW REST LIGHT INBOARD (OFCR/L IB)	BOEING	AUG 05/08	3	JUL 01/11
33-20-17	CMM	1J5005-510012-X	ENTRY AREA LIGHT 12 (EA/L 12)	BOEING	JAN 21/08	2	MAY 07/24
33-20-18	CMM	1N5005-200060-X 1N5006-100000-X	ATTENDANT WORK LIGHT	BOEING	SEP 19/08	1	JUN 29/12
33-20-19	CMM	1N5005-300000-X	THRESHOLD LIGHT (TH/L)	BOEING	SEP 30/08	0	-
33-20-20	CMM	1N5005-400000-X	DIRECT AREA LIGHT (DA/L)	BOEING	OCT 15/08	0	-
33-20-21	CMM	1X5005-300000-X	LIGHT ASSEMBLY REMOTE POWER SUPPLY (LAR/PS)	BOEING	JAN 31/08	2	MAY 07/24
33-20-30	CMM	1J5006-100012-0 1J5006-100020-0 1J5006-100035-0 1J5006-100040-0 1J5006-100050-0	SIDEWALL LIGHT	BOEING	AUG 10/11	0	-
33-20-32	CMM	1C5006-101000-0 1C5006-102000-0	REMOTE POWER SUPPLY	BOEING	MAY 16/11	0	-
33-21-01	CMM	3352-01 3352-02 3352-03 3352-12 3352-13 3352-15 3352-16	SIDEWALL AND CEILING LIGHTS	BOEING	JUL 28/94	0	-
33-21-03	CMM	3352-05	SIDEWALL LIGHT	BOEING	JUN 10/94	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-21-04	CMM	3352-21 3352-22 3352-23 3352-32 3352-32-10 3352-33 3352-33-10 3352-35 3352-35-10 3352-36 3352-36-10	SIDEWALL AND CEILING LIGHTS	BOEING	APR 01/95	2 TR	JAN 16/02 AUG 22/05
33-21-05	CMM	3352-41 3352-42 3352-43 3352-52 3352-52-10 3352-53 3352-53-10 3352-55 3352-55-10 3352-56 3352-56-10	SIDEWALL AND CEILING LIGHTS	BOEING	JUN 15/99	3 TR	SEP 10/01 AUG 22/05
33-21-06	CMM	4186-01 4186-02 4186-03 4186-04 4186-50 4186-51 4186-52 4186-53 4186-54 4186-60 4186-61 4186-62 4186-63 4186-64	SIDEWALL AND CEILING LIGHTS	BOEING	JUL 01/99	2	JUN 12/02
33-21-09	CMM	3352-06 3352-06-10	SIDEWALL LIGHT	BOEING	MAR 16/95	3	FEB 01/02
33-21-10	CMM	3352-07 3352-07-10	SIDEWALL LIGHT	BOEING	APR 30/99	1	SEP 10/01
33-21-12	TM	30841	AUTO-TRANSFORMER	AIRBUS	DEC 01/72	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-21-13	CMM	3352-62 3352-63 3352-65 3352-66	CEILING LIGHT	BOEING	OCT 30/01	1	FEB 11/05
33-21-14	CMM	4041-12 4041-18 4041-24 4041-28 4041-48 4041-58 4041-70 4042-10	CEILING LIGHT	BOEING	AUG 01/97	5	AUG 27/24
33-21-17	CMM	3250-40 3250-40-10 3250-41 3250-41-10 3250-42 3250-42-10	LIGHT ASSEMBLY	BOEING	MAR 31/99	3	FEB 02/05
33-21-19	CMM	3352-91-31700 3352-91-33100 3352-91-34200 3352-91-35200	INDIRECT COLOR LED LIGHT (ICLL)	BOEING	DEC 14/06	1	JUN 07/11
33-21-20	CMM	3352-90-12100 3352-90-13500 3352-90-14200 3352-90-15600 3352-90-23500 3352-90-24200	SIDEWALL AND CEILING LIGHTS	BOEING	FEB 23/04	8	AUG 03/12
33-21-21	CMM	3352-91-12100 3352-91-13500 3352-91-14200 3352-91-15600 3352-91-23500 3352-91-24200	SIDEWALL AND CEILING LIGHTS	BOEING	NOV 18/05	6	JUL 18/12
33-21-22	CMM	3352-93-04000	LED ART ILLUMINATION LIGHT (AIL)	BOEING	SEP 10/08	0	-
33-21-23	CMM	3352-08	SIDEWALL LIGHT	BOEING	OCT 10/01	0	-
33-21-24	CMM	3352-90-50110	AREA LIGHTING CONTROLLER (ALC)	BOEING	MAY 14/04	3	AUG 22/11

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-21-25	CMM	4279-20-00 4279-35-00 4279-40-00 4279-50-00 4279-200-00 4279-201-00 4279-202-00 4279-203-00 4279-350-00 4279-351-00 4279-400-00 4279-401-00	SIDEWALL AND CEILING LIGHTS	BOEING	JUL 31/03	1	NOV 12/04
33-21-26	CMM	3352-90-11000	SIDEWALL LIGHT 10"	BOEING	APR 30/04	5	JAN 14/11
33-21-27	CMM	3352-91-11000	SIDEWALL LIGHT 10"	BOEING	DEC 06/05	3	FEB 11/11
33-21-31	CMM	4222-50	115 VAC BALLAST UNIT T8	EMBRAER	JUN 19/24	0	-
33-21-32	CMM	4222-60	28 VDC BALLAST UNIT T8	EMBRAER	JUN 19/24	0	-
33-21-35	CMM	4270-10 4270-10-0X 4270-11 4270-11-0X 4276-10 4276-10-0X 4276-11 4276-11-0X 4276-20 4276-20-0X	DUO ADVANCED INTEGRATED BALLAST UNIT (DUO AIBU)	AIRBUS	AUG 30/02	3	FEB 25/06
33-21-36	CMM	1B5000-140000-1 1B5000-210000-1 1B5000-280000-1	DUO ILLUMINATION BALLAST UNIT (DIBU)	AIRBUS	SEP 01/05	0	-
33-21-37	CMM	1B5000-135000-1 1B5000-136000-1 1B5000-145000-1 1B5000-146000-1 1B5000-215000-1 1B5000-216000-1 1B5000-285000-1 1B5000-286000-1	FLAT ILLUMINATION BALLAST UNIT (FIBU)	AIRBUS	SEP 01/05	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-21-40	CMM	4270-50-00 4270-51-00 4276-50-00 4276-51-00 4276-60-00	RGBW ADVANCED INTEGRATED BALLAST UNIT (RGBW AIBU)	AIRBUS	OCT 16/06	1	JUN 11/24
33-21-46	CMM	1B5000-140000-X 1B5000-210000-X 1B5000-280000-X	DUO ILLUMINATION BALLAST UNIT (DIBU)	AIRBUS	MAR 05/08	3	JAN 21/12
33-21-47	CMM	1B5000-135000-X 1B5000-136000-X 1B5000-145000-X 1B5000-145100-X 1B5000-146000-X 1B5000-146100-X 1B5000-215000-X 1B5000-216000-X 1B5000-285000-X 1B5000-286000-X	FLAT ILLUMINATION BALLAST UNIT (FIBU)	AIRBUS	MAR 10/08	3	MAR 09/12
33-21-48	CMM	1A5000-130000-X 1A5000-140000-X 1A5000-210000-X 1A5000-280000-X	SINGLE ILLUMINATION BALLAST UNIT (SIBU)	AIRBUS	FEB 28/08	3	APR 30/12
33-21-49	CMM	1B5000-131100-X 1B5000-141100-X 1B5000-211100-X 1B5000-281100-X	HYBRID ILLUMINATION BALLAST UNIT (HIBU)	AIRBUS	MAR 12/08	3	MAY 11/12
33-22-01	TDS	3382-10	LAMPHOLDER	BOMBARDIER EMBRAER	APR 03/97	0	-
33-22-02	TDS	3385-20 3385-30	FLUORESCENT LAMP FIXTURE	BOMBARDIER EMBRAER	FEB 21/97	0	-
33-22-03	TDS	4048-10 4048-11 4048-20 4048-21 4048-30 4048-31 4048-40 4048-41	LAMP CARRIER	BOMBARDIER EMBRAER	APR 21/97	3	JAN 09/06

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-22-04	TDS	4049-10 4049-11 4049-20 4049-21 4049-30 4049-31 4049-40 4049-41	LAMP CARRIER	BOMBARDIER EMBRAER	FEB 21/97	3	JAN 09/06
33-22-05	TDS	4224-10 4224-30	LAMP CARRIER	EMBRAER	NOV 29/02	1	JAN 09/06
33-23-01	ACMM	3247-10 3247-15 3247-16 3247-20 3247-30 3247-32 3247-40 3247-42	BALLAST UNIT	AIRBUS FOKKER	DEC 12/06	0	-
33-23-12	CMM	3196	FLASHER	AIRBUS	NOV 01/78	1	SEP 01/79
33-23-13	CMM	3216	FLASHER	AIRBUS	OCT 15/79	0	-
33-24-12	CMM	3081-11 3081-21 3081-31 3081-41 3081-51 3081-61	BALLAST UNIT	AIRBUS	JUN 01/79	2	AUG 30/89
33-24-13	CMM	3081-25 3081-35 3081-65	BALLAST UNIT	AIRBUS	NOV 15/82	3	OCT 31/95
33-24-14	CMM	3250-20 3250-60	BALLAST UNIT	AIRBUS	AUG 01/87	1	AUG 20/92
33-24-15	CMM	3250-70	BALLAST UNIT	AIRBUS	NOV 01/89	1	DEC 04/24
33-24-16	CMM	3250-30 3250-80	BALLAST UNIT	AIRBUS	MAY 20/93	3	JUL 25/00
33-24-17	CMM	3250-20-10 3250-31 3250-70-10 3250-81	BALLAST UNIT	AIRBUS	JUN 30/23	4	FEB 05/01

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-24-18	CMM	4197-10 4197-10-0X 4197-20 4197-20-0X 4197-30 4197-30-0X	ADVANCED INTEGRATED BALLAST UNIT (AIBU)	AIRBUS	APR 30/03	3	DEC 01/24
33-24-20	CMM	1A5000-130000-1 1A5000-140000-1 1A5000-210000-1 1A5000-280000-1	SINGLE ILLUMINATION BALLAST UNIT (SIBU)	AIRBUS	SEP 01/05	0	-
33-24-21	CMM	1B5000-131100-1 1B5000-141100-1 1B5000-211100-1 1B5000-281100-1	HYBRID ILLUMINATION BALLAST UNIT (HIBU)	AIRBUS	APR 28/06	0	-
33-24-97	CMM	3367-10 3367-11	DUO BALLAST UNIT 28 V	BOMBARDIER EMBRAER	AUG 22/08	0	-
33-24-99	CMM	3253-10	BALLAST UNIT	DORNIER	FEB 20/95	2	SEP 28/01
33-25-10	ACMM	1N5000-4A00XX-0 1N5000-4B00XX-0	LED SPOTLIGHT	AIRBUS	JUL 31/06	1	JUN 27/08
33-25-20	ACMM	4264-XX-0XX00XX	WASHTABLE LIGHT	AIRBUS	SEP 02/03	0	-
33-25-21	CMM	4303-1X-XX0100X	LED STRIP LIGHT	BOEING	OCT 10/03	2	JAN 31/05
33-25-40	ACMM	4228-X0-X-XXX 4229-X0-X-XXX	LOW LEVEL LIGHT	AIRBUS	AUG 24/24	1	JUN 15/12
33-26-01	CMM	4265XXXXXXYY	LIGHT INTERFACE STANDARDIZATION ADAPTER (LISA)	AIRBUS	OCT 21/02	3	OCT 09/06
33-27-01	CMM	3352-92-50100	STAR LIGHT CONTROLLER (SLC)	BOEING	DEC 06/06	1	NOV 19/24
33-27-02	CMM	3352-98-50100	LIGHTING CONTROLLER (LC)	BOEING	DEC 12/06	1	NOV 15/24
33-31-13	ACMM	4257-10	CARGO LOADING LIGHT	EMBRAER	MAY 30/05	1	OCT 15/08
33-34-01	CMM	3294-10-1 3294-10-2 3294-20-1 3294-20-2	CARGO COMPARTMENT LIGHT	AIRBUS	MAY 25/92	3	JUN 05/00
33-34-02	CMM	4260-10 4260-10-01 4260-10-02	CARGO COMPARTMENT LIGHT	AIRBUS	MAR 31/03	2	DEC 01/24
33-34-03	CMM	1G5000-080000-0	CARGO COMPARTMENT LIGHT	AIRBUS	SEP 01/05	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-50-01	CMM	3400-22 3400-22-10	EMERGENCY LIGHT POWER UNIT (ELPU)	EMBRAER	NOV 28/02	3	DEC 05/08
33-51-01	ACMM	3301-31	BATTERY	BOMBARDIER EMBRAER SAAB	JAN 14/08	10	OCT 10/23
33-51-04	CMM	3121-01 (3121-10) (3121-11)	EMERGENCY LIGHT SUPPLY UNIT (ELSU)	AIRBUS BRITISH AEROSPACE	AUG 01/80	1	APR 02/81
33-51-05	CMM	3117-01	BATTERY	AIRBUS BRITISH AEROSPACE	JAN 15/81	1	JAN 10/00
33-51-06	CMM	3214-20 3214-40 3214-41	EMERGENCY POWER SUPPLY UNIT (EPSU)	AIRBUS	AUG 25/83	4 TR	AUG 15/02 OCT 31/06
33-51-07	CMM	3214-30	BATTERY	AIRBUS DORNIER	FEB 15/83	5	FEB 04/23
33-51-08	CMM	3214-51	EMERGENCY POWER SUPPLY UNIT	AIRBUS	FEB 01/87	0	-
33-51-09	CMM	3214-52 3214-54 3214-55	EMERGENCY POWER SUPPLY UNIT (EPSU)	AIRBUS	DEC 08/89	2 TR TR	AUG 26/94 APR 23/07 OCT 23/08
33-51-10	CMM	3214-60 3214-62	EMERGENCY POWER SUPPLY UNIT (EPSU)	AIRBUS	NOV 12/93	2	MAR 25/02
33-51-11	CMM	3214-90 3214-91 3214-92	AUTONOMOUS STANDBY POWER SUPPLY UNIT (ASPSU)	AIRBUS	APR 25/92	3	JUL 10/24
33-51-12	CMM	3214-54-10 3214-54-20 3214-55-10 3214-62-10 3214-62-20	EMERGENCY POWER SUPPLY UNIT (EPSU)	AIRBUS	DEC 01/23	3	DEC 16/05
33-51-14	OM	3121	EMERGENCY LIGHT SUPPLY UNIT (ELSU)	AIRBUS	JAN 15/74	0	-
33-51-17	CMM	3214-31	BATTERY	AIRBUS DORNIER	JUL 08/02	4	JUN 11/12
33-51-30	CMM	2A5000-100000-X 2A5000-101000-X	EMERGENCY POWER SUPPLY UNIT (EPSU)	AIRBUS	APR 18/06	2	MAR 30/12
33-51-40	CMM	2C5000-150000-X	BATTERY	AIRBUS	JUL 14/06	1	APR 29/08
33-51-41	CMM	2C5000-170000-X	BATTERY	AIRBUS	MAY 16/08	2	DEC 02/11

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
33-51-95	CMM	3400-20	EMERGENCY LIGHT POWER SUPPLY (ELPS)	BOMBARDIER	AUG 15/96	3	JUN 25/24
33-51-96	CMM	3301-11 3301-51	EMERGENCY LIGHT POWER SUPPLY (ELPS)	SAAB	MAR 01/96	2	AUG 21/03
33-51-97	CMM	3301-50	EMERGENCY LIGHT POWER SUPPLY (ELPS)	SAAB	SEP 20/94	1	NOV 14/94
33-51-98	CMM	3301-10	EMERGENCY LIGHT POWER SUPPLY (ELPS)	SAAB	JUN 01/93	0	-
33-51-99	CMM	3214-73	EMERGENCY POWER SUPPLY UNIT (EPSU)	DORNIER	SEP 01/94	2	JUL 02/24
33-52-01	ACMM	4274-10-06 4275-00-20000 4275-10-00000 4275-12-10000 4275-21-10280	DOME LED LIGHT (DOLLI)	AIRBUS	OCT 28/03	0	-
38-13-11	CMM	VT061-1	WATER QUANTITY TRANSMITTER	AIRBUS	-	4	DEC 14/01
38-13-12	CMM	VT442	WASTE WATER QUANTITY INDICATOR	AIRBUS	-	5	NOV 27/01
38-13-13	CMM	DK033 DK033-3	PRESSURE TRANSMITTER	AIRBUS	-	4	MAR 30/01
38-13-14	CMM	DK453	PRESSURE INDICATOR	AIRBUS	-	2	MAR 30/01
38-13-15	CMM	VT061-2 (MODA, AMDTB)	WATER QUANTITY TRANSMITTER	AIRBUS	-	5	JUN 02/24
38-13-16	CMM	DK481	WATER PRESSURE INDICATOR	AIRBUS	-	4	FEB 12/02
38-13-17	CMM	DK063	WATER PRESSURE TRANSMITTER	AIRBUS	-	1	MAR 30/01
38-13-18	CMM	KM436 (AMEND. A)	LCD COMBI - PANEL	AIRBUS	-	3	MAR 30/01
38-13-20	CMM	VT061-7 VT061-71 VT061-71A VT061-71B VT061-9 VT061-9A VT061-9B	WATER CONTENTS TRANSMITTER	AIRBUS	-	6	APR 30/24
38-14-11	CMM	VT442-2	WATER QUANTITY INDICATOR	AIRBUS	-	4	SEP 14/01
38-14-12	CMM	VT476-11	POTABLE WATER QUANTITY INDICATOR	AIRBUS	-	1	MAR 30/01
38-40-02	CMM	DK118-2	PRESSURE SWITCH	AIRBUS	-	3	MAR 30/01
52-71-10	CMM	9852070085 9852070346 700201E01010100 700201E01010200	DOORS AND SLIDES MANAGEMENT CONTROL UNIT (DSMCU)	AIRBUS	MAY 12/06	3	JUL 30/24
52-71-11	CMM	700201M00030302 700201M00040302	PROCESSOR CONTROL MODULES (PCM)	AIRBUS	APR 24/24	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

ATA Reference	Doc. Type	Part Numbers	Nomenclature	Aircraft Manufacturer	Initial Issue	Revision	
						No.	Date
52-71-12	CMM	700201M00020100	POWER SUPPLY MODULE (PSM)	AIRBUS	JUN 17/24	0	-
52-71-13	CMM	2852071058	INTER CONNECTION UNIT (ICU)	AIRBUS	JAN 30/24	0	-
52-71-20	CMM	9852080295 9852080381 700301E01010100 700301E01010200	LOCAL DOOR CONTROLLER (LDC)	AIRBUS	MAY 12/06	4	JUL 28/24
52-71-21	CMM	9002500116	CONTROL CHANNEL MODULE (CCM) (LDC)	AIRBUS	JUN 27/08	2	SEP 09/24
52-71-22	CMM	1002510201	VOTING INPUT/ OUTPUT MODULE (VIOM) (LDC)	AIRBUS	JUN 27/08	2	SEP 10/24
52-71-24	CMM	700301M00020100	INTER CONNECTION UNIT (ICU) (LDC)	AIRBUS	JUN 27/08	0	-
52-71-25	CMM	1853060067 (UD) 1853060098 (MD)	FAN UNIT (FAU)	AIRBUS	JUL 28/06	1	DEC 03/24
52-71-26	CMM	9002540121	DOOR EMERGENCY POWER SUPPLY (DEPS-S2)	AIRBUS	MAR 17/24	1	DEC 10/24
52-71-26	CMM	9002540121	DOOR EMERGENCY POWER SUPPLY (DEPS-S2)	AIRBUS	MAR 17/24	1	DEC 10/24
52-71-30	CMM	9882150016 D01201E02010100	AUTONOMOUS STANDBY POWER SUPPLY UNIT (ASPSU)	AIRBUS	JAN 20/06	2	AUG 13/24
52-71-40	ACMM	1942020002 1942020040	SWIVEL ACTUATOR (SWA)	AIRBUS	APR 28/06	2	JAN 25/24
52-71-45	ACMM	1942040006 1942040020 1942040037	FLIGHT LOCK / DE-ARREST ACTUATOR	AIRBUS	JUN 09/2008	1	AUG 11/24
52-71-61	ACMM	1910790009	DIFFERENTIAL PRESSURE SWITCH (DPS)	AIRBUS	MAR 14/05	0	-
52-71-90	ACMM	2883 SERIES 7001 SERIES	DOOR WIRING	AIRBUS	MAY 05/06	1	DEC 11/24

SB Index:

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
065-50000-27-001	065-50000-0404	MODIFICATION OF PART NO. 065-50000-0304 TO PART NO. 065-50000-0404 OR REPAIR OF PART NO. 065-50000-0404	AIRBUS	-	REV 2	AUG 18/03	
065-50000-27-003	065-50000-0508	MODIFICATION OF PART NO. 065-50000-0404 TO PART NO. 065-50000-0508	AIRBUS	-	REV 0	AUG 30/02	
065-50000-27-004	065-50000-0509	MODIFICATION OF PN 065-50000-0508	AIRBUS	-	REV 0	AUG 20/03	

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
065-50001-27-001	065-50001-0200	CONVERSION TO PNR 065-50001-0200 AMENDMENT B	AIRBUS	-	REV 0	FEB 07/12	
185306-52-001	185306SERIES	THERMAL IMPROVEMENT OF THE FAN UNIT (FAU)	AIRBUS	-	REV 2	DEC 03/24	
194202-52-001	1924770202	SWIVEL ACTUATOR : USE OF SELF SECURED HELICOIL INSERTS AND DIFF. COLOR.	AIRBUS	-	REV 0	NOV 02/24	
194204-52-001	194204SERIES	HELICOIL MODIFICATION AND GLUE CONNECTION BETWEEN MAGNET AND ROTOR FOR MAGNETIC SPRING (FLDAA)	AIRBUS	-	REV 2	SEP 08/08	
1A5000-33-01	1A5000-XX0000-X	SIBU: INTRODUCTION OF NEW PNR 1A5000-XX0000-4	AIRBUS	AUG 10/24	REV.0	-	CMM 33-21-48
1A5000-33-02	1A5000-XX0000-X	SIBU: NEW AMDT A FOR PNR 1A5000-XX0000-4	AIRBUS	AUG 24/24	REV.0	-	CMM 33-21-48
1B5000-33-01	1B5000-XXXXX00-X	FIBU: INTRODUCTION OF NEW PNR 1B5000-XXXXX00-4	AIRBUS	AUG 10/24	REV.0	-	CMM 33-21-47
1B5000-33-02	1B5000-XX0000-X	DIBU: INTRODUCTION OF NEW PNR 1B5000-XX0000-4	AIRBUS	AUG 10/24	REV.0	-	CMM 33-21-46
1B5000-33-03	1B5000-XX1100-X	HIBU: NEW PNR 1B5000-XX1100-4 AMDT A	AIRBUS	OCT 21/24	REV.1	NOV 08/24	CMM 33-21-49
1B5000-33-04	1B5000-XXXXX00-X	FIBU: NEW AMDT A FOR PNR 1B5000-XXXXX00-4	AIRBUS	AUG 24/24	REV.0	-	CMM 33-21-47
1B5000-33-05	1B5000-XX0000-X	DIBU: NEW AMDT A FOR PNR 1B5000-XX0000-4	AIRBUS	AUG 24/24	REV.0	-	CMM 33-21-46
1B5000-33-06	1B5000-XX1100-X	HIBU: NEW AMDT A FOR PNR 1B5000-XX1100-4	AIRBUS	AUG 24/24	REV.0	-	CMM 33-21-49
2A5000-33-01	2A5000-100000-X	EPSU: INTRODUCTION OF NEW PNRS	AIRBUS	DEC 04/07	ISS.01	-	CMM 33-51-30
2C5000-33-02	2C5000-170000-X	BATTERY: IMPROVEMENT OF INTERNAL WIRING	AIRBUS	APR 09/24	REV.0	-	CMM 33-51-41
3081-33-001	3081-25 3081-35 3081-65	BU: IMPROVEMENT OF COMPONENTS	AIRBUS	MAR 25/87	REV.0	-	CMM 33-24-13
3081-33-002	3081-21 3081-31 3081-41 3081-61	BU: IMPROVEMENT OF COMPONENTS AND AMENDT E	AIRBUS	MAR 25/87	REV.1	APR 13/87	CMM 33-24-12
3081-33-003	3081-21 3081-31 3081-41 3081-61	BU: IMPROVEMENT OF RELAIS RL1 - RL2 AND AMDT F	AIRBUS	MAY 24/88	REV.1	APR 14/89	CMM 33-24-12
3081-33-004	3081-25 3081-35 3081-65	BU: IMPROVEMENT OF UNIT AND AMDT C	AIRBUS	SEP 15/95	REV.0	-	CMM 33-24-13
321440-33-1	3214-40 3214-41	EPSU: PREVENTION OF WATER INGRESS	AIRBUS	MAY 20/94	REV.1	SEP 26/94	CMM 33-51-06
321451-33-1	3214-51	EPSU: PNR 3214-51 SUPERSEDED BY PNR 3214-52 (REF. CMM 33-51-09)	AIRBUS	JUN 15/89	REV.0	-	CMM 33-51-08

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
321452-33-1	3214-52	EPSU: CORRECTION OF TEST RESULT	AIRBUS	JUL 27/90	REV.0	-	CMM 33-51-09
321452-33-2	3214-52 3214-54	EPSU: MODIFICATION FROM PNR 3214-52 TO PNR 3214-54	AIRBUS	JUN 25/93	REV.0	-	CMM 33-51-09
321460-33-1	3214-60 3214-62	EPSU: IMPROVEMENT OF CIDS COMMUNICATION	AIRBUS	FEB 28/95	REV.0	-	CMM 33-51-10
321473-33-01	3214-73	EPSU: IMPROVEMENT OF RELIABILITY	DORNIER	-	REV.1	JUL 15/99	CMM 33-51-99
321490-33-1	3214-90 3214-91	ASPSU: IMPROVEMENT OF CIDS COMMUNICATION	AIRBUS	JUN 12/95	REV.0	-	CMM 33-51-11
321492-33-01	3214-92	ASPSU: INTRODUCTION OF NEW PNR 3214-92	AIRBUS	DEC 19/07	REV.4	NOV 25/08	CMM 33-51-11
3224-25-01	3224-50 3224-51	MODIFICATION OF HEATING PANEL PNR 3224-50 TO PNR 3224-51	AIRBUS	APR 09/24	REV. 1	APR 12/24	CMM 25-15-51
325060-33-1	3250-60	BALLAST UNIT: AMDT B	AIRBUS	MAR 15/89	REV.0	-	CMM 33-24-14
3284-26-01	3284-11 3284-12	AFECU: IMPROVEMENT OF SYSTEM TEST FUNCTION	AIRBUS	OCT 31/96	REV.1	JUL 09/97	CMM 26-22-01
3285-30-01	3285-10	WHCU: MODIFICATION FROM AMDT A TO AMDT C	DORNIER	OCT 30/23	REV.0	-	CMM 30-42-02
3294-33-01	3294-10-1 3294-10-2 3294-20-1 3294-20-2	CCL: MODIFICATION OF PNR 3294-X0-1 TO PNR 3294-X0-2	AIRBUS	OCT 31/96	REV.0	-	CMM 33-34-01
3352-21-01	3352-22 3352-23 3352-32 3352-35	SW/L, C/L: REPLACEMENT OF PCB AND COVER (ID "M3")	BOEING	OCT 08/96	REV.1	DEC 06/96	CMM 33-21-04
3352-21-02	3352-33 3352-36	C/L: REPLACEMENT OF PCB AND COVER (ID "M3")	BOEING	OCT 08/96	REV.1	DEC 06/96	CMM 33-21-04
3352-21-04	3352-06 3352-21 3352-22 3352-23	SW/L: IMPROVEMENT OF LENS RETENTION	BOEING	JUN 08/23	ISS.0	-	CMM 33-21-09 CMM 33-21-04
3352-33-002	3352-90-50110	ALC: DEFECTIVE FLASH MEMORY (MOD A)	BOEING	FEB 21/05	ISS.1	MAR 29/05	CMM 33-21-24

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
3352-33-01	3352-05 3352-06 3352-07 3352-12 3352-13 3352-15 3352-16 3352-32 3352-33 3352-35 3352-36 3352-52 3352-53 3352-55 3352-56	SW/L, C/L: MODIFICATION OF PNR 3352-XX TO PNR 3352-XX-10	BOEING	JUN 20/01	ISS.1	MAY 29/02	CMM 33-21-01 CMM 33-21-03 CMM 33-21-04 CMM 33-21-05 CMM 33-21-09 CMM 33-21-10
3352-33-03	3352-91-24200 3352-91-23500 3352-91-12100 3352-91-13500 3352-91-14200 3352-91-15600	SW/L, C/L (CELS): SWAPPED LAMP HOLDER WIRING	BOEING	SEP 10/08	REV.0	-	CMM 33-21-21
4041-33-01	4041-12 4041-18 4041-24 4041-28 4041-48 4041-58 4041-70 4042-10	C/L: MODIFICATION TO MODE	BOEING	MAR 03/24	REV.0	-	CMM 33-21-14
4186-50-01	4186-50 4186-51 4186-52 4186-53 4186-54	C/L: MODIFICATION OF PNR 4186-5X TO PNR 4185-6X	BOEING	SEP 27/01	ISS.1	DEC 18/03	CMM 33-21-06
4190-24-01	4190-00 4190-01	SI 2500 VA: MODIFICATION OF PNR 4190-00 TO PNR 4190-01	AIRBUS	FEB 27/04	ISS.1	-	ACMM 24-28-11
4197-33-01	4197-10-01 4197-20-01 4197-30	AIBU: MODIFICATION TO PNR 4197-X0-02	AIRBUS	DEC 18/03	ISS.1	-	CMM 33-24-18
4253-33-001	4253-10	LED EMERG. EXIT SIGN HOUSING: MODIFICATION TO AMDT A	EMBRAER	MAY 09/05	ISS.1	-	—

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
4270-33-01	4270-10-01 4270-11-01 4276-10-01 4276-11-01 4276-20-01	DUO AIBU: MODIFICATION OF PNR 427X-XX-01 TO PNR 427X-XX-02	AIRBUS	DEC 18/03	ISS.1	-	CMM 33-21-35
7001-52-001	7001SERIES	RELOCATION OF CONFIGURATION CONNECTOR (DCR-140)	AIRBUS	FEB 09/2012	REV 0	FEB 09/2012	ACMM 52-71-90
700201E01-52-001	985207SERIES	INTRODUCTION OF A NEW DSMS SYSTEM SOFTWARE VERSION (L3.21A) (DSMCU)	AIRBUS	-	-	JUN 08/08	
700201E01-52-002	700201E01010100	DSMCU BONDING RESISTANCE (DSMCU)	AIRBUS	-	-	MAR 18/24	
700201E01-52-003	985207SERIES	INTRODUCTION OF A NEW DSMS SYSTEM SOFTWARE VERSION (L3.32A) (DSMCU)	AIRBUS	-	REV 0	APR 09/24	
700201E01-52-004	700201E01020300, 700201M00030502, 700201M00040502	INTRODUCTION OF DSMCU SOFTWARE L3.4 AND HW MODIFICATIONS	AIRBUS	FEB 14/2012	REV 0	FEB 14/2012	CMM 52-71-10, CMM 52-71-13
700301E01-52-001	985208SERIES	INTRODUCTION OF A NEW DSMS SYSTEM SOFTWARE VERSION (L3.21A) (LDC)	AIRBUS	-	-	JUN 18/08	
700301E01-52-002	985208SERIES	IMPROVEMENT IN THE OPERATION OF THE CCM AND VIOM BOARDS (LDC)	AIRBUS	-	REV 1	-	
700301E01-52-003	985208SERIES	INTRODUCTION OF A NEW DSMS SYSTEM SOFTWARE VERSION (L3.32A) (LDC)	AIRBUS	-	REV 0	APR 09/24	
700301E01-52-004	9002500116 AMDT A/B	ROBUSTNESS IMPROVEMENT OF CCM BOARD	AIRBUS	MAR 03/11	REV 1	AUG 25/11	CMM 52-71-21
700301E01-52-005	9002540121	IMPROVEMENT OF DERATING FOR TANTAL CAPACITORS WITH 28V OPERATIONAL VOLTAGE. HARMONISATION OF COMPONENT VARIANTS	AIRBUS	MAR 03/11	REV 2	JAN 11/2012	CMM 52-71-26
700301E01-52-006		INTRODUCTION OF LDC HARDWARE MODIFICATIONS	AIRBUS	FEB 16/2012	REV 0	FEB 16/2012	CMM 52-71-20, CMM 52-71-21, CMM 52-71-24, CMM 52-71-26
84320-27-001	84320-00-0405 DAX688432094-05	MODIFICATION OF PART NO. 84320-00-0404 TO 84320-00-0405 AND OF PART NO. DAX698432094-04 TO DAX688432094-05	AIRBUS	-	REV 1	JUL 01/2008	
84333-27-001	84333-00-0304	IMPROVEMENT OF WING TIP BRAKE LATCH RELAY ROBUSTNESS	AIRBUS	-	REV 0	AUG 10/24	
84333-27-002	84333-00-0305	INTRODUCTION OF NEW SOFTWARE WITH IMPROVED OPERATIONAL STABILITY	AIRBUS	-	REV 0	OCT 06/24	
87145-27-001	87145-00-04	FLIGHT CONTROLS - FLAP POSITION PICK-OFF UNIT (PPU) RECHECK OF CERTAIN UNITS	AIRBUS	-	REV 0	DEC 13/2010	

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SB Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue		CMM ATA Reference
					No.	Date	
CCA-90A-27-21	065-50000-0304	MODIFICATION OF PART NO. 065-50000-0202, -0303, AND -0304	AIRBUS	-	REV 0	MAY/95	
CCA-90A-27-22	065-50000-0304	MODIFICATION OF PART NO. 065-50000-0202, -0303, AND -0304	AIRBUS	-	REV 0	OCT/95	
CCA-90A-27-23	065-50000-0304	MODIFICATION OF PART NO. 065-50000-0202, -0303, AND -0304	AIRBUS	-	REV 0	DEC/96	
CCA-90A-27-24	065-50000-0404	MODIFICATION OF PART NO. 065-50000-0304 TO PART NO. 065-50000-0404	AIRBUS	-	REV 0	01.07.1998	
SB DK033-38-001	DK033	PRESSURE TRANSMITTER	AIRBUS	-	-	AUG 31/83	
SB DK033-38-002	DK033 DK033-3	PRESSURE TRANSMITTER	AIRBUS	-	-	MAR 88	
SB VT061-38-01	VT061-1	WATER QUANTITY TRANSMITTER	AIRBUS	-	-	MAY 77	
SB VT061-71-38-001	VT061-7	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	FEB 17/93	
SB VT061-9-38-001	VT061-9	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	FEB 17/93	

SIL Index:

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
3081-33-05/88	3081-X1	BALLAST UNIT: REPLACEMENT OF RELAYS	AIRBUS	MAY 11/88	0	-
3092-33-01/88	3092	TRANSFORMER: NEW LABELS	AIRBUS	JUN 30/88	0	-
3214-30-01/01	3214-30	BATTERY: IDENTIFICATION OF ORIGINAL DIEHL BATTERIES	AIRBUS DORNIER	SEP 09/01	0	-
3214-33-01/01	3214-54-10 3214-54-20 3214-55-10 3214-62-10 3214-62-20	EPSU: LOGIC BOARD ASSY (COMPUTER BOARD)	AIRBUS	MAY 21/01	1	OCT 26/24
3214-33-01/02	3214-5X 3214-5X-X0 3214-6X 3214-6X-X0	EPSU: NEW TEST UNIT	AIRBUS	JAN 11/02	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
3214-33-01/03	3214-31	BATTERY: REWORK FOR BATTERY CHARGER	AIRBUS DORNIER	FEB 14/03	0	-
3214-33-01/04	3117-01 3214-30 3214-31 3301-31	NEW BATTERY ANALYZER CADEX C7400ER-C	AIRBUS BOMBARDIER BRITISH AEROSPACE EMBRAER DORNIER SAAB	JUN 07/04	2	APR 17/08
3214-33-01/05	2A5000-10X000-X 2C5000-150000-X 2C5000-170000-X 3117-01 3121-X1 3214-3X 3214-4X/ 5X/ 6X 3214-73 3214-9X 3301-X1 3400-2X 4188-0X 4190-0X 9882150016 D01201E02010100	SHELF LIFE INFO FOR POWER SUPPLIES, BATTERIES & STATIC INVERTERS	AIRBUS BOMBARDIER BRITISH AEROSPACE EMBRAER DORNIER SAAB	MAR 01/05	7	APR 19/12
3214-33-01/87	3214-30	BATTERY: MOD. STATUS FROM 'A' TO 'B'	AIRBUS DORNIER	JUL 15/87	0	-
3214-33-01/91	3214-52	EPSU: RELIABILITY	AIRBUS	MAY 24/91	0	-
3214-33-01/92	3214-52	EPSU: BATTERY REPLACEMENT	AIRBUS	MAR 06/92	0	-
3214-33-01/94	3214-5X	EPSU: TEACH-IN AFTER POWER RESET	AIRBUS	AUG 25/94	1	-
3214-33-01/99	3214-5X 3214-6X	TEST EQUIPMENT FOR EPSU PNR 3214-5X AND 3214-6X SERIES	AIRBUS	JUL 15/99	1	APR 27/24
3214-33-02/01	3214-6X	EPSU: COMPUTER PCB	AIRBUS	AUG 01/01	0	-
3214-33-02/02	3214-30 3214-31	BATTERY: NEW P/N 3214-31	AIRBUS DORNIER	JAN 16/02	0	-
3214-33-02/92	3214-52	EPSU: MICRO CRACKS ON DC/DC CONVERTER PCB	AIRBUS	NOV 10/92	0	-
3214-33-02/94	3214-9X	ASPSU: NEW PART NUMBER	AIRBUS	NOV 09/94	1	-
3214-33-03/02	3214-30	BATTERY: LIFETIME AND STORAGE TIME	AIRBUS DORNIER	APR 22/02	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
3214-33-04/02	3214-54-20 3214-62-20	EPSU: CONVERTER U11 ON POWER SUPPLY PCB	AIRBUS	JUN 17/02	1	FEB 25/24
3214-33-04/88	3214-30	BATTERY: BATTERY EXCHANGE	AIRBUS DORNIER	DEC 15/88	0	-
3214-33-05/02	3214-5X-X0 3214-6X-X0	EPSU: SELF-ADHESIVE STRIPS	AIRBUS	AUG 29/02	1	NOV 22/24
3214-33-06/05	3214-31	BATTERY: AMENDMENT B	AIRBUS DORNIER	DEC 05/05	1	-
3224-25-01/91	3224-50	OBSOLESCENCE OF SIL	AIRBUS	MAR 26/91	2	MAR 16/24
3250-33-01/00	3250-20 3250-20-10 3250-60 3250-70 3250-70-10	BALLAST UNIT: NEW PART NUMBERS	AIRBUS	FEB 01/02	1	-
3250-33-01/91	3250-60	BALLAST UNIT: SEALING OF THE IGNITION CIRCUIT	AIRBUS	JAN 10/91	0	-
3250-33-01/94	3250-30 3250-80	BALLAST UNIT: AMENDMENT STATUS OF UNITS	AIRBUS	NOV 22/94	1	-
3250-33-01/95	3250-80	BALLAST UNIT: AMENDMENT B	AIRBUS	SEP 01/95	1	-
3250-33-01/96	3250-80	BALLAST UNIT: AMENDMENT C	AIRBUS	FEB 26/96	1	-
3250-33-01/97	3250-80	BALLAST UNIT: AMENDMENT D	AIRBUS	SEP 15/97	0	-
3250-33-02/88	3250-60	BALLAST UNIT: DIMMABLE TUBES	AIRBUS	DEC 14/88	0	-
3250-33-02/94	3250-20 3250-30 3250-60 3250-70 3250-80	BALLAST UNIT: INTERCHANGEABILITY	AIRBUS	DEC 20/94	1	-
3284-26-01/05	3284-14	AFECU: AMENDMENT A	AIRBUS	SEP 01/05	1	-
3284-26-01/96	3284-1X	AFECU: CHANGE OF PART NUMBERS	AIRBUS	JUL 23/96	1	-
3301-33-01/95	3301-10 3301-50	ELPS: BATTERY HANDLING	SAAB	JUL 14/95	1	-
3301-33-01/96	3301-11 3301-51	ELPS: STORAGE	SAAB	MAY 31/96	0	-
33-24-13/01	3081-65	BALLAST UNIT: MODIFICATION A	AIRBUS	SEP 18/84	0	-
33-51-04/01	3121-10	MAINTENANCE OF ELSU PN 3121-10	AIRBUS BRITISH AEROSPACE	NOV 15/82	0	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
33-51-04/02	3121-11	MAINTENANCE OF ELSU PN 3121-11	AIRBUS BRITISH AEROSPACE	SEP 20/84	0	-
3352-33-01/01	3352-07 3352-08 3352-5X 3352-6X	SIDEWALL AND CEILING LIGHTS: NEW CONNECTOR	BOEING	JUN 20/01	0	-
3352-33-01/06	3352-4X 3352-5X 3352-5X-XX	IMPROVED CAPACITORS C45/C46	BOEING	MAR 22/06	0	-
3352-33-02/01	774-125-36 774-142-11	JUMPER CABLE: NEW INTERFACE CONNECTOR	BOEING	JUN 20/01	0	-
3367-33-01/02	3367-10	BALLAST UNIT: LAMP CARRIER HANDLING	BOMBARDIER EMBRAER	FEB 04/02	0	-
3367-33-01/23	3367-10	BALLAST UNIT: AMENDMENT A	BOMBARDIER EMBRAER	OCT 30/23	0	-
3400-33-01/05	3400-20	ELPS: AMENDMENT A	BOMBARDIER	SEP 15/05	1	-
3400-33-01/06	3400-20	ELPS: AMENDMENT B	BOMBARDIER	JAN 26/06	2	MAR 15/06
4197-33-01/03	4197-X0 4197-X0-0X	AIBU: NEW PART NUMBERS	AIRBUS	DEC 18/03	1	FEB 17/04
4265-33-01/03	4265XXXXXXYY	LISA: NEW IDENTIFIER FOR CONTROL MODULE	AIRBUS	FEB 26/03	0	-
4270-33-01/03	4270-1X 4276-XX	DUO AIBU: NEW PART NUMBERS	AIRBUS	FEB 17/03	0	-
4270-33-02/03	4270-1X 4276-XX	DUO AIBU: NEW PART NUMBERS	AIRBUS	DEC 18/03	1	FEB 17/04
774-23-001	774-028-XX 774-029-XX 774-056-9X	CREW CALL SYSTEM (CCS): RELEVANT PCBS AND ADAPTERS	AIRBUS	APR 26/88	0	-
D1347-25-001	3224-50 3224-51	INTRODUCTION OF NEW PNR 3224-51	AIRBUS	AUG 27/08	0	-
D1347-33-001	3214-30 3214-31 3301-31	DIEHL NICD BATTERIES: SAFETY INSTRUCTIONS	AIRBUS BOMBARDIER EMBRAER DORNIER SAAB	JUL 18/06	2	APR 17/12
D1347-33-002	2C5000-150000-X	DIEHL LITHIUM-ION BATTERIES: SAFETY INSTRUCTIONS	AIRBUS	JUL 19/06	1	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
D1347-33-003	3117 3117-01	DIEHL NICD BATTERY PN 3117 SERIES: SAFETY INSTRUCTIONS	AIRBUS BRITISH AEROSPACE	JUL 18/06	1	-
D1347-33-004	3400-22	EMERGENCY LIGHT POWER UNIT: AMENDMENT A	EMBRAER	JUL 18/06	1	-
D1347-33-005	3400-22	EMERGENCY LIGHT POWER UNIT: AMENDT B	EMBRAER	JUL 18/06	1	-
D1347-33-006	3367-10 3367-11 3367-21	BALLAST UNITS PN 3367-XX: FUNCTIONAL DIFFERENCES	BOMBARDIER EMBRAER	FEB 16/07	1	-
D1347-33-007	3352-01 3352-02 3352-03 3352-05 3352-06 3352-06-10 3352-07 3352-07-10 3352-08 3352-21 3352-22 3352-23 3352-41 3352-42 3352-43	HISTORY OF LENS DEVELOPMENT	BOEING	MAR 12/07	1	-
D1347-33-009	4270-50-00 4270-51-00 4276-60-00	RGBW AIBU: AMENDT A	AIRBUS	MAR 22/07	1	-
D1347-33-010	1A5000-XX0000-X 1B5000-XXXX00-X	PNR HISTORY FOR XIBU FAMILY	AIRBUS	MAY 30/08	2	JUN 29/24
D1347-33-017	3400-22 3400-22-10	ELPU: INTRODUCTION OF NEW PNR 3400-22-10	EMBRAER	JUL 16/08	3	DEC 03/08
D1347-33-018	2C5000-150000-X	OBSOLESCENCE OF A380 EPSU BATTERY	AIRBUS	SEP 01/08	1	SEP 22/08
D1347-33-019	3400-22-10	REWORK OF PNR 3400-22-10 S/N 5001 THRU 5480	EMBRAER	SEP 29/08	2	JUL 23/24
D1347-33-020	2C5000-170000-0 2C5000-170000-1	INTRODUCTION OF NEW PNR FOR A380 BATTERY	AIRBUS	MAR 16/24	0	-
D1347-33-021	1A5000-XX0000-X 1B5000-XXXX00-X	INTRODUCTION OF NEW PNRS FOR XIBU FAMILY	AIRBUS	MAR 25/24	0	-
D1347-33-022	2A5000-100000-3 2A5000-101000-3	INTRODUCTION OF NEW PNR CONFIGURATION FOR EPSU	AIRBUS	APR 24/24	0	-
D1347-33-023	3352-90-XXX00	BROKEN CAPACITOR IN TOKEN CIRCUIT	BOEING	AUG 20/24	1	JAN 26/24

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
D1347-33-024	3352-90-XXX00 3352-91-XXX00	BLOWN LIGHT FIXTURE FUSE F1	BOEING	AUG 20/24	0	-
D1347-33-025	2C5000-150000-X 2C5000-170000-X	INTRODUCTION OF SOFTWARE UPDATE FOR BATTERY TESTER PNR C8000-D	AIRBUS	JUL 17/24	0	-
D1347-33-026	3400-20	ELPS: AMENDMENT C	BOMBARDIER	JAN 27/24	0	-
D1347-33-027	4260-10 4260-10-0X	INTRODUCTION OF NEW PNR FOR CCL	AIRBUS	JAN 28/24	1	APR 16/24
D1347-33-028	4197-X0 4197-X0-0X	INTRODUCTION OF NEW PNR FOR AIBU	AIRBUS	APR 16/24	0	-
D1347-33-029	3214-62-32	SRPSU: AMDT C FOR PNR 3214-62-32	AIRBUS	DEC 09/11	1	JAN 20/12
D1347-33-031	2C5000-170000-X	DIEHL LITHIUM-ION BATTERIES: SAFETY INSTRUCTIONS	AIRBUS	JUL 14/24	0	-
D1347-33-032	4197-31-02	AIBU: OBSOLESCENCE OF PNR 4197-31-02	AIRBUS	SEP 27/24	0	-
D1347-33-034	2C5000-150000-1 2C5000-170000-X	STORAGE INFORMATION ON A380 BATTERY	AIRBUS	JUN 01/11	0	-
D1347-33-035	ALL	LATEST TEST EQUIPMENT VERSIONS	AIRBUS BOEING	OCT 07/11	3	JUL 19/12
D1347-33-036	2C5000-150000-X 2C5000-170000-X	ADDITIONAL INFORMATION ON BATTERY ANALYZER PNR C800-D	AIRBUS	OCT 21/11	0	-
D1347-33-037	4197-X0 4197-X0-0X	AIBU: AMDT A FOR PNR 4197-X0-04	AIRBUS	APR 16/12	0	-
D1347-33-038	4260-10 4260-10-0X	CCL: AMDT A FOR PNR 4260-10-02	AIRBUS	APR 16/12	0	-
D1347-33-039	2A5000-101000-3	IDENTIFICATION OF MODIFIED EPSU	AIRBUS	DEC 13/11	1	DEC 16/11
D1347-33-040	1B5000-XX0000-4	DIBU: AMDT B FOR PNR 1B5000-XX0000-4	AIRBUS	MAR 05/12	0	-
D1347-33-041	1B5000-XXXXX00-4	FIBU: AMDT B FOR PNR 1B5000-XX0000-4	AIRBUS	MAR 05/12	0	-
D1347-33-042	1A5000-XX0000-4	SIBU: AMDT B FOR PNR 1A5000-XX0000-4	AIRBUS	MAR 05/12	0	-
D1347-33-043	1B5000-XX1100-4	HIBU: AMDT B FOR PNR 1B5000-XX1100-4	AIRBUS	MAR 05/12	0	-
D1347-33-044	1J5005-1000XX-2	SW/L: NEW PNR SERIES 1J5005-1000XX-2	BOEING	FEB 14/12	0	-
D1347-33-046	3214-31	BATTERY: AMDT C	AIRBUS DORNIER	APR 16/12	0	-
DAS/SIL/38-13-15/0003	VT061-2	WATER QUANTITY TRANSMITTER	AIRBUS	-	-	MAY 02/07
DAS/SIL-0001	ALL	SOLDER TO BE USED FOR PCB REPAIR	AIRBUS	MAY 10/07	1	-
P3214-33-01/23	P3214-51	TEST SET FOR EPSU PNR 3214-54 AND 3214-55	AIRBUS	MAY 25/23	1	-

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
SIL 01-99	065-50000-XXXX	CHANGE OF MANUFACTURER	AIRBUS	-	0	AUG 02/99
SIL 02-03	300-90115-XXXX 884331320000000 984331320000000	INTRODUCTION OF A SECOND SOURCE FOR THE SOLID STATE RELAYS.	AIRBUS	-	1	MAR 12/04
SIL 03-04	065-50000-0XXXX 284331011100000	INTRODUCTION OF A LEAKAGE CURRENT TEST OF LEMP/EMI ASSEMBLY FOR A BATCH OF SFCC	AIRBUS	-	1	MAR 18/04
SIL 04-05	065-50000-0404 065-50000-0508 065-50000-0509	REDUCTION OF OPERATIONAL INTERRUPTS CAUSED BY CLASS 1 FAILURES ATTRIBUTABLE TO THE HIGH LIFT SYSTEM BY IMPROVEMENT OF SFCC ROBUSTNESS.	AIRBUS	-	2	JUN 16/05
SIL 05-07	065-50000-0509	BATCH OF SUSPECTED PROGRAMMABLE FILTER U9 (S3528B), USED ON THE PSU BOARDS OF SLAT FLAP CONTROL COMPUTER (SFCC).	AIRBUS	-	0	APR 16/07
SIL KM436-001	KM436 (AMEND. A)	LCD COMBI-PANEL	AIRBUS	-	-	MAR 01/89
SIL VT061-001	VT061-1 VT061-2	WATER QUANTITY TRANSMITTER	AIRBUS	-	-	MAY 03/90
SIL VT061-002	T061-1 VT061-2 MOD A VT061-8	WATER QUANTITY TRANSMITTER	AIRBUS	-	-	JAN 31/91
SIL VT061-003	VT061-9 VT061-71	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	AUG 03/92
SIL VT061-004	VT061-7 VARIANTS VT061-9 VARIANTS	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	AUG 31/95
SIL VT061-005	VT061-7 VARIANTS VT061-9 VARIANTS	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	SEP 12/96
SIL VT061-006	VT061-9 VARIANTS	WATER CONTENTS TRANSMITTER	AIRBUS	-	-	MAY 28/97
SIL001-86	774-028-90	CREW CALL SYSTEM (CCS): MODIFICATION A FOR AMPLIFIER PCB	AIRBUS	APR 30/86	0	-
SIL002-86	3081-X1	BALLAST UNIT: DEFECTIVE CAPACITOR C3	AIRBUS	MAY 07/86	0	-
SIL003-86	3081-X1 3081-X5	BALLAST UNIT: RELAY FAILURE	AIRBUS	MAY 07/86	0	-
SIL004-86	3081-X5	BALLAST UNIT: DEFECTIVE CAPACITOR C3	AIRBUS	JUN 06/86	0	-
VSIL D2439-29-001	VT477 VT477-1	HYDRAULIC RESERVOIR QUANTITY INDICATOR	AIRBUS	-	-	OCT 14/24
VSIL D2439-52-002	1940440013 1940440037	INTRODUCTION OF A380-XXX PITCH ATTITUDE SENSOR (PAS) IMPROVEMENT	AIRBUS	-	1	MAR 11/08
VSIL D2439-52-003	1974180048 1974180055	INTRODUCTION OF AN IMPROVEMENT OF RPL-PAX AND RPL-PAX 3	AIRBUS	-	1	SEP 09/24

DIEHL

Aerospace

DIEHL Aerospace GmbH (Vendor Code D1347+D2439+D4829): Tech Pubs Index (CMM, SB and SIL) for all Aircraft

SIL Number	Part Numbers	Subject	Aircraft Manufacturer	Initial Issue	Revision / Issue	
					No.	Date
VSIL D2439-52-004	700701E00010100 700701E00010200	INTRODUCTION OF A380-XXX NEW RESIDUAL PRESSURE WARNING HORN (RPWH)	AIRBUS	-	-	JAN 27/24
VSIL D2439-52-005	2C5000-150000-X	INTRODUCTION OF NEW ASPSU BATTERY PACK	AIRBUS	-	-	FEB 20/24
VSIL D2439-52-006	D01201E02010100	INTRODUCTION OF NEW ASPSU PNR CONFIGURATION (988215SERIES)	AIRBUS	-	-	APR 03/24
VSIL D2439-52-006	D01201E02010100	INTRODUCTION OF NEW ASPSU PNR CONFIGURATION (988215SERIES)	AIRBUS	-	1	JUL 15/24
VSIL D2439-52-007	1940430047	INTRODUCTION OF NEW PNR FOR A380-XXX SENSOR TARGET CIRCULAR TYP 2 (PROX TAC2) (SENSORIC)	AIRBUS	-	1	DEZ 03/24
VSIL D2439-52-008	700301E01010200 A	INTRODUCTION OF PREVENTIVE EXCHANGE OF A380-800 LOCAL DOOR CONTROLLER (LDC)	AIRBUS	-	-	AUG 25/24
VSIL D2439-52-009	700301E01010200 A	CHANGES IN THE LDC HOUSING IN A380 LOCAL DOOR CONTROLLER (LDC)	AIRBUS	-	0	JUL 26/24
VSIL D2439-52-010	700301P00160100	INTRODUCTION OF A380-LOCAL DOOR CONTROLLER (LDC) STORAGE CONTAINER	AIRBUS	-	0	JAN 27/11
VSIL D2439-52-1012	700301E01010X00	INTRODUCTION OF A MOD KID FOR A380 LOCAL DOOR CONTROLLER (LDC) DESCRIBED IN SB 700301E01-52-002, 004 AND 005.	AIRBUS	AUG 24/11	0	AUG 24/11
VSIL D2439-GN-0001	TM113-1 VT061-9 VT061-71 VT442-2 VT476-11 VT477-2, -3	REFERENCE TO LABELS WITH OLD AND NEW COMPANY LOGOS IN SBS AND SILS WATER CONTENTS TRANSMITTER WATER QUANTITY INDICATOR POTABLE WATER QUANTITY INDICATOR	AIRBUS	-	-	FEB 19/24
VSIL-D4829-27-007	200301E00000206 065-50001-0200	INTRODUCTION OF A NEW SLAT FLAP CONTROL COMPUTER (SFCC) AND A NEW COMMAND SENSOR UNIT (CSU) INTO THE A320 FAMILY.	AIRBUS	-	0	DEC 15/24
VSIL-D4829-27-008	065-50001-0200	INTRODUCTION OF A NEW AMENDMENT OF THE COMMAND SENSOR UNIT (CSU) INTO THE A330/340 AND A320 FAMILY.	AIRBUS	-	0	APR 23/11
VSIL-D4829-27-009	84320-00-0X0X, 0684320043400	REPLACEMENT OF OLD WTB BOARD SLAT STANDARD (PNR 0684320043400 AMDT A AND B) BY NEW ONE (PNR 0684320043400 AMDT C)	AIRBUS	-	0	FEB 20/12
VSIL-D4829-27-010	84333-00-0305, 284333083200000, 284333043200000	EXCHANGE OF A SPECIFIC LOT OF I/O BOARDS SLAT PNR 284333083200000 AMENDMENT E AND I/O BOARDS SLAT/FLAP PNR 284333043200000 AMENDMENT E.	AIRBUS	-	0	APR 24/12

List of Abbreviations: ¹⁾

ACMM	Abbreviated Component Maintenance Manual
ATL	ATLAS Test Specification
ATPM	Automatic Test Procedure Manual
ATS	ATLAS Test Specification
CMM	Component Maintenance Manual
IPC	Illustrated Parts Catalogue
OM	Overhaul Manual
OPNC	Optional Part Number Catalog
SB	Service Bulletin
SIL	Service Information Letter
TDS	Technical Data Sheet
TIS	Technical Information Sheet
TM	Technical Manual
TR	Temporary Revision

¹⁾ if applicable